



11. EXPLODED VIEW AND PART LIST

11-1.THE PART LIST OF CABINET ASSEMBLY



11-2. THE EXPLODED VIEW OF CONTROL PANEL &



This diagram is an exploded view of a mechanical assembly, likely a pump or motor component. It shows the main housing and various internal and external parts. The components are labeled with codes in circles: F140, K411, K410, K350, K360, K143, K123, K121, K122, K125, K320, K105, K410, K115, K110, K141, K111, F320, F310, F466, F464, K140, K510, K130, K135, K530, K512, K131, F468, K520, F461, K540, K346, K571, K572, K570, K550, K610, K611. The diagram uses dashed lines to indicate the assembly path and alignment of the parts.

